



Transport  
Canada

Transports  
Canada

## Transports Canada – Vehicle Recall Register



A CAA-Quebec Presentation

Publication date : August 5, 2008

### CARS, MOTORCYCLES, TRAILERS, RECREATIONAL VEHICLES

---

**Recall:** 2008229 GOODYEAR      **Date:** Jun 27, 2008      **Vehicles:** unknown

Certain tires fail to comply with the requirements of CMVSS 109 - Passenger Car Tires. Specifically, these tires fail to meet the plunger energy test standard for an "Extra Load" labeled tire. These tires were designed and manufactured for use in European and other countries, and not intended for sale in North America. Correction: Dealers will replace tires with North American compliant versions.

**Models Involved**

DUNLOP WINTER SPORT 3D 225/50R17  
DUNLOP WINTER SPORT M3 275/35R18

---

**Recall:** 2008218 KAWASAKI - ATV08-01      **Date:** Jun 23, 2008      **Vehicles:** 170

On certain youth-model ATVs, the throttle may not return to the idle position during vehicle operation. Should this occur, it could result in a loss of vehicle control causing a crash with property damage, personal injury, or death. Correction: Dealers will replace the carburetor assembly.

**Models Involved**

2008 KAWASAKI KFX50  
2008 KAWASAKI KFX90

---

**Recall:** 2008219 WINNEBAGO      **Date:** Jun 24, 2008      **Vehicles:** 39

On certain motorhomes equipped with a Norcold Inc. refrigerator, a fatigue crack in the section of the cooling unit which contains the refrigerant could allow the liquid solution to slowly leak. If a leak occurs and the refrigerator continues to be operated after solution circulation has ceased, hydrogen gas may be expelled and can be ignited. This could result in a fire, causing property damage, personal injury, or death. Correction: Dealers will replace the refrigerators cooling unit.

**Models Involved**

2000-2002 ITASCA HORIZON  
1999 ITASCA SUNCRUISER  
2001 ITASCA SUNFLYER  
2000 ITASCA SUNRISE  
2000-2001 WINNEBAGO BRAVE  
1999-2001 WINNEBAGO CHIEFTAIN  
2001 WINNEBAGO JOURNEY  
2000 WINNEBAGO MINNIE WINNIE  
1999-2002 WINNEBAGO ULTIMATE ADVANTAGE  
1999-2002 WINNEBAGO ULTIMATE FREEDOM

---

**Recall:** 2008220 COACHMEN      **Date:** Jun 24, 2008      **Vehicles:** 2,003

On certain motorhomes, conventional travel trailers and fifth wheel travel trailers equipped with a Dometic Corporation refrigerator, a fatigue crack can develop in the boiler tube. This could allow the release of pressurized coolant solution into an area where an ignition source is present, which could result in a fire. Note: This is an expansion of recall 2007053. Correction: Dealers will replace the refrigerator's boiler tube assembly.

**Models Involved**

2006-2008 ADRENALINE FIFTH WHEEL TRAILER  
2006-2007 ADRENALINE TRAVEL TRAILER  
2004-2007 COACHMEN AURORA MOTORHOME  
2007-2008 COACHMEN CAPRI MICRO TRAVEL TRAILER  
2004-2007 COACHMEN CAPRI TRAVEL TRAILER  
2004-2007 COACHMEN CAPTIVA TRAVEL TRAILER  
2004-2006 COACHMEN CASCADE TRAVEL TRAILER  
2005 COACHMEN CATALINA FIFTH WHEEL TRAILER  
2004 COACHMEN CATALINA LITE TRAVEL TRAILER  
2004-2005 COACHMEN CATALINA TRAVEL TRAILER  
2005-2007 COACHMEN CHAPARRAL FIFTH WHEEL TRAILER  
2004-2007 COACHMEN CHAPARRAL TRAVEL TRAILER  
2004 COACHMEN CHEYENNE MOTORHOME  
2004-2007 COACHMEN CONCORDE MOTORHOME  
2004-2007 COACHMEN CROSS COUNTRY MOTORHOME  
2004-2006 COACHMEN CROSS COUNTRY SPECIAL EDITION  
2006-2007 COACHMEN EPIC MOTORHOME  
2004-2008 COACHMEN FREEDOM MOTORHOME  
2004-2008 COACHMEN FREELANDER MOTORHOME  
2004 COACHMEN FREEPORT MOTORHOME  
2007 COACHMEN GRAND HEAVEN TRAVEL TRAILER  
2004-2007 COACHMEN LEPRECHAUN MOTORHOME  
2004 COACHMEN MIRADA LIBERTY EDITION MOTORHO  
2004-2007 COACHMEN MIRADA MOTORHOME

2004 COACHMEN OASIS TRAVEL TRAILER  
2004 COACHMEN RENDEZVOUS MOTORHOME  
2004 COACHMEN REVERE MOTORHOME  
2004 COACHMEN ROADMASTER MOTORHOME  
2004-2006 COACHMEN SANTARA MOTORHOME  
2003-2004 COACHMEN SOMERSET DREAMCATCHER FIFTH WH  
2005 COACHMEN SOMERSET FIFTH WHEEL TRAILER  
2006 COACHMEN SOMERSET TRAVEL TRAILER  
2004-2007 COACHMEN SPIRIT OF AMERICA TRAVEL TRAIL  
2006 COACHMEN VELOCITY TRAVEL TRAILER  
2007 COACHMEN WYOMING FIFTH WHEEL TRAILER  
2005 GEORGIE BOY BELLAGIO MOTORHOME  
2005-2006 GEORGIE BOY CRUISE AIR XL MOTORHOME  
2005-2006 GEORGIE BOY CRUISE MASTER LIMITED EDITION  
2005-2006 GEORGIE BOY CRUISE MASTER MOTORHOME  
2005-2007 GEORGIE BOY LANDAU MOTORHOME  
2006-2008 GEORGIE BOY MAVERICK MOTORHOME  
2005-2007 GEORGIE BOY PURSUIT MOTORHOME  
2005-2007 SPORTSCOACH ENCORE MOTORHOME  
2004-2005 SPORTSCOACH LEGEND MOTORHOME  
2007 SPORTSCOACH PATHFINDER MOTORHOME

---

**Recall:** 2008221 NISSAN      **Date:** Jun 24, 2008      **Vehicles:** 4,134

Certain 2005-2006 model year vehicles may have been assembled with an incorrectly manufactured air conditioning condenser fan motor, which could allow excessive water intrusion and inadequate drainage. If sufficient moisture accumulates in the motor, corrosion could occur, increasing internal friction, and thereby augmenting the electrical current draw. This could cause an increase in the motors operating temperature that could eventually melt its wiring insulation and other plastic components and form a gas. If two wires without insulation touch each other and create a spark, this gas could ignite and result in a vehicle fire, which could cause property damage, personal injury or death. Note: 2004, and some 2005 model year vehicles are equipped with a different fan motor that is not subject to this campaign. However, it is possible that a limited number of these vehicles may have received the subject condenser fan as a service replacement part, thereby being included in this action. Correction: Dealers will affect repairs.

**Models Involved**

2004-2006 INFINITI QX56  
2004-2006 NISSAN ARMADA  
2004-2006 NISSAN TITAN

---

**Recall:** 2008223 TIFFIN      **Date:** Jun 26, 2008      **Vehicles:** 7

On certain vehicles, the fasteners that attach the steering arm or tie rod arm to the spindle may have been over or under tightened during assembly process. Incorrectly torqued steering arm fasteners may fatigue and fracture, possibly causing a crash without warning. Correction: Dealers will inspect fasteners and apply correct tightening torque.

**Models Involved**

2007-2008 TIFFIN PHAETON

---

**Recall:** 2008225 DAMON      **Date:** Jun 26, 2008      **Vehicles:** 45

On certain motorhomes equipped with a Norcold Inc. refrigerator, a fatigue crack in the section of the cooling unit which contains the refrigerant could allow the liquid solution to slowly leak. If a leak occurs and the refrigerator continues to be operated after solution circulation has ceased, hydrogen gas may be expelled and can be ignited. This could result in a fire, causing property damage, personal injury, or death. Correction: Dealers will replace the refrigerators cooling unit.

**Models Involved**

1999 DAMON ESCAPER  
1999 DAMON INTRUDER  
1999 DAMON ULTRASPORT

---

**Recall:** 2008226 TRIPLE E      **Date:** Jun 26, 2008      **Vehicles:** 9

On certain motorhomes, incorrect fasteners may have been used to attached the brake caliper to the brake anchor plate during vehicle assembly. The incorrect fasteners may not provide adequate clamping force, potentially resulting in reduced brake effectiveness. Extended stopping distances may result in a vehicle crash causing injury or death. Correction: Dealers will inspect and, if incorrect bolts are found, will check for possible additional damage, and repair as required.

**Models Involved**

2008 TRIPLE E INVITATION

---

**Recall:** 2008228 FOREST RIVER      **Date:** Jun 27, 2008      **Vehicles:** 1,222

On certain travel trailers equipped with a Dometic Corporation refrigerator, a fatigue crack can develop in the boiler tube. This could allow the release of pressurized coolant solution into an area where an ignition source is present, which could result in a fire. Note: This is an expansion of recall 2007091. Correction: Dealers will replace the refrigerator's boiler tube assembly.

**Models Involved**

2003-2006 PALOMINO STAMPEDE  
2003-2006 PALOMINO THOROUGHbred

---

**Recall:** 2008230 FOREST RIVER      **Date:** Jun 27, 2008      **Vehicles:** unknown

On certain motorhomes, conventional travel trailers and fifth wheel travel trailers equipped with a Dometic Corporation refrigerator, a fatigue crack can develop in the boiler tube. This could allow the release of pressurized coolant solution into an area where an ignition source is present, which could result in a fire. Correction: Dealers will replace the refrigerator's boiler tube assembly.

**Models Involved**

2004-2006 FOREST RIVER ALL AMERICAN SPORT  
2004-2006 FOREST RIVER AUTO MASTER  
2004-2006 FOREST RIVER AUTO PLUS  
2004-2006 FOREST RIVER CARDINAL  
2004-2006 FOREST RIVER CEDAR CREEK  
2004-2006 FOREST RIVER CHEROKEE  
2004-2006 FOREST RIVER ELIMINATOR

2004-2006 FOREST RIVER FLAGSTAFF  
2004-2006 FOREST RIVER FORESTER  
2004-2006 FOREST RIVER GEORGETOWN  
2004-2006 FOREST RIVER GRAND SURVEYOR  
2004-2006 FOREST RIVER LEXINGTON  
2004-2006 FOREST RIVER LEXINGTON GT  
2004-2006 FOREST RIVER MB CRUISER  
2004-2006 FOREST RIVER QUALIFIER  
2004-2006 FOREST RIVER ROCKWOOD  
2004-2006 FOREST RIVER SALEM  
2004-2006 FOREST RIVER SANDPIPER  
2004-2006 FOREST RIVER SIERRA  
2004-2006 FOREST RIVER SUNSEEKER  
2004-2006 FOREST RIVER SURVEYOR  
2004-2006 FOREST RIVER TSUNAMI  
2004-2006 FOREST RIVER WILDCAT  
2004-2006 FOREST RIVER WILDWOOD  
2004-2006 FOREST RIVER WORK AND PLAY

---

**Recall:** 2008231 MONACO - R08018      **Date:** Jul 02, 2008      **Vehicles:** 51

On certain motorhomes, the Liquid Propane (LP) gas line may have been routed incorrectly during vehicle assembly. As a result, the LP line may become entangled with the 12 Volt and 120 Volt wiring which could cause the hose to kink and/or become damaged, possibly resulting in a leak. A propane gas leak, in the presence of an ignition source, could result in a fire or an explosion, which could cause property damage, personal injury or death. Correction: Dealers will replace and reroute the LP line.

**Models Involved**

2008 HOLIDAY RAMBLER ADMIRAL SE  
2007-2009 HOLIDAY RAMBLER ARISTA  
2009 SAFARI IVORY  
2008 SAFARI IVORY SE  
2007-2008 SAFARI PASSAGE

---

**Recall:** 2008232 JAYCO      **Date:** Jul 02, 2008      **Vehicles:** 17

On certain fifth wheel trailers, the isolating rubber boot, located atop electrical connectors within the towing harness, may not have been installed correctly during vehicle assembly. As such, depending which connector becomes exposed and shorts to ground, 1). An electrical short could occur, which could result in a vehicle fire, 2). Loss of driving lights may result in the driver's intentions to turn or brake not being conveyed clearly to other road users, as well as making the vehicle less conspicuous during hours of reduced visibility, 3). Loss of trailer braking function, which could extend stopping distances. All these conditions could result in property damage, personal injury, or death. Correction: Dealers will inspect the rubber caps, and correct as needed.

**Models Involved**

2009 JAYCO DESIGNER 5TH WHEEL  
2009 JAYCO EAGLE 5TH WHEEL  
2009 JAYCO RECON 5TH WHEEL